

NOTICE 通告

瑜翠園各住戶：

PDC-2025-N042

更換泳池地下喉管工程

茲通知各業戶，由於泳池地下喉管出現滲漏，承辦商現正進行更換喉管工程，更換喉管後需進行全面的壓力測試以確保系統運作正常，並需修復及還原受損泳池地面。工程完成後將進行清潔及池水水質檢測。由於工程及後續工作需時，故泳池重新開放時間將可能因此延後，我們將在所有上述工程程序順利完成後再公佈最新開放時間。

服務處將會密切監察工程進度。如有任何查詢，請於辦公時間內致電 2458 7256 與本處職員聯絡。



瑜翠園服務處 啟

2025 年 3 月 29 日

To: All Residents of Peridot Court

Date: 29 March 2025

Replacement Work of Underground Pipe in Swimming Pool

We regret to inform you that due to a detected leakage underground pipe of the swimming pool, contractor is carrying out replacement works. This will be followed by pressure test to ensure system integrity and restoration of affected pool surfaces. Deep cleaning and water testing will also be arranged afterwards. Due to the time required for the subsequent work, pool's reopening may be postponed. We will provide updates regarding the opening schedule once all procedures are successfully completed.

Management Service Office will closely monitor the progress of the replacement work. Should you have any queries, please contact our staff at 2458 7256 during office hour.

Peridot Court

Management Services Office

通告張貼至 2025 年 5 月 6 日
This notice will be posted until 6 May 2025



詳情請瀏覽網站：www.peridotcourt.info

Visit the estate website for details. Website: www.peridotcourt.info

KAI SHING
MANAGEMENT SERVICES
啟勝管理服務
PMC Licence No: C-499163

啟勝管理服務有限公司
Kai Shing Management Services Limited